

DEPARTMENT OF TRANSPORTATION
DIVISION OF ENGINEERING SERVICES
MATERIALS ENGINEERING AND TESTING SERVICES
5900 FOLSOM BOULEVARD
SACRAMENTO, CA 95819-4612
PHONE (916) 227-7266
FAX (916) 227-7117



*Flex your power!
Be energy efficient!*

March 2, 2011

Bankim Shukla
Shankar Upadhyaya
Quality Manager
JSW Steel (USA), Inc
5200 E McKinney Road
Baytown, TX 77523

Dear Mr. Shukla and Mr. Upadhyaya:

The California Department of Transportation has determined that an audit has been successfully completed for the following:

Facility: JSW Steel USA, Inc. at Baytown, Texas
Product: Non-Redundant (Class N) & Redundant (Class R) Structural Steel Pipe Piling
Longitudinal Seam Submerged Arc Welded Pipe

Range of Pipe Sizes


Minimum Diameter 24" and Maximum Thickness 0.75"

Maximum Diameter 48" and Maximum Thickness 1.00"

The validity of this audit will expire at the end of March 2014. JSW Steel USA, Inc. is responsible for notifying the Department of any changes to the audit and supporting documents, and shall submit updated documents within two weeks of any changes for approval in writing, to the Chief of the Quality Assessment and Management Branch, Office of Structural Materials, 5900 Folsom Blvd., Sacramento, CA 95819. A submittal shall include a cover letter detailing all changes and referencing all supporting documents. Failure to notify the Department of any changes relative to this audit may result in invalidation of the audit. Please plan accordingly to also submit an electronic copy (pdf) of all required documents.

Should you have any questions or concerns please feel free to contact John Yang at (916) 227-7264 or john_z_yang@dot.ca.gov. Thank you for participating in the Department's Facility Audit.

Sincerely,



BRETT SOLDANO
Chief
Quality Assessment and Management Branch
Office of Structural Materials

c: Tim Greutert, Chief, Quality Assurance and Source Inspection, Sacramento
Sang Le, Chief, Quality Assurance and Source Inspection, Los Angeles
Keith Hoffman, Chief, Quality Assurance and Source Inspection, Vallejo
File